


1. UPPER LEVEL INACCESSIBLE FOR PROGRAMATIC USES.
2. KILN LOCATION DANGEROUS.
3. SCIENCE LAB INADEQUATE, OBSOLETE, AND DANGEROUS.
4. MASONRY IN NEED OF REPOINTING THROUGH-OUT.
5. AREAS OF MASONRY TO BE REPOINTED/REBUILT.
6. LIBRARY USED BY ELEMENTARY SCHOOL FROM OUTSIDE.
7. INADEQUATE STORAGE FOR INDIVIDUAL CLASSROOMS/TEACHERS.
8. BULGING WALL AT EXTERIOR MASONRY.



HIGH SCHOOL BUILDING - EXISTING CONDITIONS

CROWLEY COUNTY SCHOOL DISTRICT
 SEPTEMBER 2008